



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:2

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਬਠਿੰਡਾ।

ਫੋਨ ਅਤੇ ਫੈਕਸ: 3161-2212428

email - xenc2btl@gmail.com

ਸੰਖਿਆ ਨੰ: 5548

ਮਿਤੀ: 12/03/2024

ਦੱਸ

Principal
The Millennium School
HMEL Township, Bathinda, Punjab (151301)

ਦਿਸ਼ਾ: ਬਿਲਡਿੰਗ ਮੋਡਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਰਵਾਲਾ: ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ- TMS/HMEL/23-24/0020 ਮਿਤੀ 28.02.2024

ਉਪਰੋਕਤ ਦਿਸ਼ਾ ਤੇ ਰਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ, ਨਿਰੀਖਣ ਦੌਰਾਨ ਖਾਣਿਆ ਗਿਆ ਹੈ ਕਿ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਮੋਡ ਹੈ। ਇਸ ਲਈ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਹੇਠ ਲਿਖੀਆਂ ਸ਼ਰਤਾਂ ਅਧੀਨ 31.03.2025 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ ਮੋਡਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।


1. The Structure safety Certificate dated 26.02.2024 is provided by Er. Babbi Singh, Singh Architects Ajit Road Bathinda and as per his certificate the school is safe to be occupied for session 2024-25, and is fit for normal use only, however no structure drawing approved as per earthquake resistant norms has been provided by the school authority hence the structural safety of the building can not be ensured specially from earthquake point of view by this department.
2. In case any addition, alteration, expansion and modification to this building are required / to be done, regarding this, inspection of undersigned must be arranged and fresh a certification after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of wall foundation etc. Immediately inspection of the undersigned must be arranged to check the stability and safety of the building.
4. A separate certificate regarding Electrical works should be obtained from the competent authority.
- 4A. **Fire Fighting Certificate should be obtained from competent authority and it should be renew time to time. If the certificate will not be renewed then this office building safety certificate becomes invalid from the very date. In this case Fire Safety Certificate renewal date is 19.09.2024**
5. The owner of the building/Management should be responsible to address any repair issues that could compromise the safety of the building, in spite of this report the school management is fully responsible regarding safety of the building from all angles.
6. The school should have a comprehensive emergency response plan in place, including procedures for evacuation, lockdowns, and communication during emergencies. The school must regularly review and update this plan to ensure its effectiveness.
7. The school should provide appropriate safety training to staff members, including procedures for handling emergencies, first aid, and evacuation protocols.
8. The fee has been charged for the area as mentioned in the drawing by the school authority. The corresponding fee charges for the year 2024-25 Rs. Ten Thousand only (10,000) vide GR No. 1745202 Dated 04.03.2024.
9. This report is not valid for legal purpose.

ਨੋਬੀ/ਸਰਟੀਫਿਕੇਟ ਅਤੇ ਨਕਸ਼ਾ

ਪਿੱਠ ਅੰਕਣ -


 ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
 ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ
 ਬਠਿੰਡਾ
 ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 3 ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਬਠਿੰਡਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਦਫਤਰ ਦੇ ਪੱਤਰ ਨੰ 309 ਮਿਤੀ 07.03.2024 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਮੋਡਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।


 ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
 ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ
 ਬਠਿੰਡਾ।